

# Honda Recall certain 2018-2021 GL1800 Goldwing motorcycles



WASHINGTON, D.C. – November 11, 2024 – (Motor Sports NewsWire) –

## Honda Recall – Drive Gear Bolt on Crankshaft May Break

*An engine stall and rear wheel lockup can increase the risk of a crash or injury.*

NHTSA Campaign Number: 24V820000

Manufacturer: Honda (American Honda Motor Co.)

Components: ENGINE AND ENGINE COOLING

Potential Number of Units Affected: 18,196

**Summary:** Honda (American Honda Motor Co.) is recalling certain 2018-2021 GL1800 Goldwing motorcycles. The primary drive gear bolt on the crankshaft may break, which can result in an engine stall and lock up the rear wheel.

**Remedy:** Dealers will replace the primary drive gear bolt, free of charge. Owner notification letters are expected to be mailed December 20, 2024. Owners may contact Honda customer service at 1-866-784-1870. Honda's number for this recall is KQ9.

**Notes:** Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153) or go to [nhtsa.gov](https://www.nhtsa.gov).

*Source: National Highway Traffic Safety Administration*